

466




FIG 1




FIG. 2




FIG. 3

Incoming Mail Processing




FIG. 4




Fig. 5

00000000000000000000000000000000

**PRINT OF DRAWINGS  
AS ORIGINALLY FILED**




FIG. b

**PRINT OF DRAWINGS  
AS ORIGINALLY FILED**





FIG. 7

Bu



F15, 8

### Message Transmission Failure




FIG. 9

00098614 - 001798

**PRINT OF DRAWINGS  
AS ORIGINALLY FILED**

0909660-417998






FIG. 10

FIG. 11




PRINT OF DRAWINGS  
AS ORIGINALLY FILED

FIG. 12




81627190-41286060

FIG 13



362790-47986060


FIG 14




PRINT OF DRAWINGS  
AS ORIGINALLY FILED


00003614-1990-00000

FIG. 15







**PRINT OF DRAWINGS  
AS ORIGINALLY FILED**



**PRINT OF DRAWINGS  
AS ORIGINALLY FILED**



**PRINT OF DRAWINGS  
AS ORIGINALLY FILED**



8627500-#TTG06050

**PRINT OF DRAWINGS  
AS ORIGINALLY FILED**

8627T90-11T986000

Fig. 20




Fig. 21

卷之三

